

H007

T

pristav	0:00	0	30z							
Z001	0:04	1	30z							
Z079	0:06	2	30z							
Z080	0:08	3	30z							
Z081	0:11	4	25o	30	38o					
Z082	0:13	5	00	20	40	41o				
Z083	0:16	6	00	01o	10	20	30	40	50	
Z084	0:18	7	01	01	10	20	30	40	50	
Z085	0:19	8	02	01	10v	20	30	40		
Z018	0:21	9	00	10v	20	30v	40			
Z086	0:23	10	00	20	40					
Z087	0:26	11	00	20	40					
Z088	0:28	12	00	20	40					
Z089	0:33	13	00	20	21o	40	41o			
Z027	0:36	14	00	01o	10	20	30	40	50	
Špičky smyčka	0:37	15	00	10	20	30	40	50		
		16	00	10	20	30	40	50		
		17	00	10	20	30	40	50		
		18	00	10v	20	30v	40			
		19	00	20	40					
		20	00	20	40					
		21	00	25	35v	55				
		22	25	55						
		23	25oz	30z						

Špičky, smyčka	0:00	0							
Z027	0:02	1							
Z089	0:05	2							
Z088	0:10	3							
Z087	0:12	4	20o	35o					
Z086	0:14	5	00	16o	20	40	56o		
Z018	0:16	6	00	10	20	30	40	50	
Z085	0:18	7	00	10	20	30	40	50	
Z084	0:20	8	00	10	20	30	40v	50	
Z083	0:23	9	10	20v	30	50			
Z082	0:25	10	10	30	50				
Z081	0:27	11	10	30	50				
Z080	0:30	12	10	30	50				
Z079	0:32	13	10	26o	30	46o	50		
Z001	0:34	14	00	10	20	30	40	50	
přístav	0:38	15	00	10	20	30	40	50	
		16	00	10	20	30	40	50	
		17	00	10	20	30	40	50	
		18	00	10	20v	30	40v	50	
		19	10	30	50				
		20	10	30	50				
		21	15	25v	45				
		22	15	45v					
		23	05v	35v					

Z194	0:00	23	46						
Z087	0:02	0	46						
Z086	0:04	1	46						
Z018	0:06	2	46						
Z085	0:08	3	46						
Z084	0:10	4	46						
Z083	0:13	5							
Z082	0:15								
Z081	0:17								
Z080	0:20								
Z079	0:22								
Z001	0:24								
přístav	0:28								

v = do vozovny
o = odjezd z vozovny
z = do smyčky Z194